

Radiogram 5999u

Form 24 for 06.25.03

Hardware Upgrade

GMT	Crew	Activity
06:00–06:10		Morning inspection
06:10–06:40		Post-sleep
06:40–07:30		BREAKFAST
07:30–07:55	CDR	Prep for work
07:30–08:00	FE-1	
07:55–08:00	CDR	PLANTS-2: payload status check
08:00–08:15		Daily planning conference (<i>S-band</i>)
08:15–09:45	CDR	БРПК hardware upgrade
08:15–11:15	FE-1	RED repairs
09:45–11:15	CDR	
11:15–12:30	FE-1	Physical exercise (TVIS)
11:15–11:35	CDR	БРПК hardware upgrade
11:35–12:35		Physical exercise (VELO + Load Trainer 1 / day 4)
12:30–12:35	FE-1	Weekly maintenance of TVIS
12:35–13:35		LUNCH
13:35–14:15	FE-1	Maintenance of COЖ
13:35–14:00	CDR	MOLNIYA-SM: payload recovery. Tagup w/ ground specialist (<i>S-band</i>)
14:00–15:15		MOLNIYA-SM: payload setup for test w/ AGATE monitor. Tagup w/ ground specialist (<i>S-band</i>)
14:15–14:55	FE-1	IMS file prep
14:55–15:05		FMK stowage
15:05–15:15		PCBA setup
15:15–15:35	CDR	MOLNIYA-SM: payload recovery. Tagup w/ ground specialist (<i>S-band</i>)
15:15–15:35	FE-1	PCBA blood test
15:35–16:05		RED bolt maintenance
15:35–15:50	CDR	MOLNIYA-SM: payload teardown. Tagup w/ ground specialist (<i>S-band</i>)
15:50–15:55		HEMATOCRIT: test setup
16:10–16:20	FE-1	Setup for PAO event
16:20–16:30		Prep for PAO event
16:30–16:50		PAO event: NEMO/ISS-7 crew conference (<i>Ku+S-band</i>)
16:50–17:05	FE-1	Routine inspection of RED
16:50–18:20	CDR	Physical exercise (TVIS-4)
17:05–18:20	FE-1	Physical exercise (RED)
18:20–18:30		Payload status check
18:20–18:45	CDR	Daily plan review
18:30–18:45	FE-1	
18:45–19:00		Daily planning conference (<i>S-band</i>)
19:00–19:30		Prep for work
19:30–20:00		DINNER

20:00–20:30		Daily food prep
20:30–21:30		Pre-sleep
21:30–06:00		SLEEP

See OSTP for references to US activities.

End of radiogram